Sunbeam Tiger Stock Class Concourse

Typical Deductions

The following is a list of typical deductions from the total points possible in each category. It does <u>not</u> represent the total list of possible deductions.

Engine Compartment

Missing or incorrect VIN Plate	-2 to -4
Missing or incorrect JAL # tag	0.5-1
Engine compartment color differs from	-2
exterior color	
Non-stock oil filter assembly	-2
Non-stock or incorrect washer bottle	0.5-1
Assy.	
Incorrect air filter assembly	-1
Non-stock air filter element	-0.5
Incorrect generator / alternator	-1
Incorrect water pump	-1
Incorrect block color	-1
Incorrect coil / location	-1
Incorrect distributor	-1 to -2
Incorrect /missing brake booster	-1 to -2
Incorrect radiator / shroud / fan	-1 to -3
Incorrect heater control valve	-1
Incorrect hoses and clamps	-0.5 to -2
Valve covers / oil fill cap	-0.5 to -2
Incorrect Brake Master / Cup	-0.5 to -1
Incorrect Clutch master / Cap	-0.5 to -1
Incorrect Wiring harness / routing/ Color	-0.5 to -2
of wrapping and wires	
Incorrect PCV valve	-0.5
Incorrect brake lines / routing	-0.5
Incorrect ballast resistor	-0.5
Incorrect fasteners (other than noted)	-0.5
Powder coated anything	-1 to -2

Dip stick incorrect	-0.5
Horns, missing or incorrect	-0.5 to -2
Incorrect carburetor and/or intake	-0.5 to -2
manifold (non-Holley square bowl or	
non-Autolite)	

Chassis

Rear disc brakes (non LAT 46 or	-1.5
equivalent)	
Non-OEM steering housing	-2
Non-OEM rack	-4
Non stock inner tie rod links	-1
Non stock steering arms	-1
Non-Top Loader nor BW T-10 tranny	-2
Front cross member aftermarket,	-0.5 to -4
incorrect and/or powder coated	
Differential pumpkin	
(if not completely black)	-0.5 to -2
Incorrect tailpipes/hangers	-0.5
Sway bar larger than 7/8" diameter	-0.5
Fender walls not undercoated	-0.5
Incorrect shocks (Shocks Black	-0.5
Armstrong stock / Koni or Traction	
Master)	
Panhard rod missing or incorrect	-0.5 to -2
Front brakes other than stock	-0.5 to -2
Drop Spindles	-1
Non Stock or missing fasteners	-0.5 to -2
Torque arm installed	-1
Incorrect fuel pump and/or lines	-0.5 to -2
Incorrect brake hoses	-0.5
Front fender valences clearanced	-0.5
Incorrect mufflers	-0.5

Interior

Seats: Aftermarket or incorrectly	-0.5 to -2
restored	
Non-stock steering wheel	-0.5 to -2
Non-stock instruments	-0.5 to -2
Non-stock shifter	-0.5 to -2
Non-original Center Console	-2
Incorrect dash board, lower finisher	-0.5 to -2
and dash pad	
Carpet	-0.5 to -2
Roll Bar	-2.0
Turn signal lever	-0.5 to -1
4-point Seat belts	-1
(no deduction for 3-point)	
Upholstery Material	-0.5 to -2
Radio / Housing / Speakers	-0.5 to -1
Hood pull and fresh air vents incorrect	-0.5 to -1
Door threshold and finisher incorrect	-0.5 to -1
E-brake handle incorrect	-0.5 to -1
Interior chrome incorrect / missing	-0.5 to -2

Exterior

Incorrect paint	-1 to -4 ,
Non-Stock Wheels (LAT 70, 31, 9 ok)	-2
Chrome or stainless trim: missing trim	-0.5 to -2
items	
Glass / Plexiglass missing or not visible	-0.5 to -2
Non-original bias ply tires	0
Radial tire, rating minimum 200	-1

High performance radial tires, tread-	-4
wear rating under 200	
Tail Lights: incorrect screw or lens	0.5 to -1
Rolled or cut fender lips	-0.5 to -2
Non LAT flares or fender warping	-0.5 to -3
Incorrect Reverse lights	-1
Body panel gaps and alignment	-0.5 to -2
Bumpers, overriders and fasteners	-0.5 to -2

Trunk

Spare tire does not match road tires	-1
Incomplete or Missing tool kit	-0.5 to -1.5
Jack assembly (jack and handle should	-0.5 to -1
be original and in stock clips)	
Non-stock battery cable terminal ends	-1
Incorrect battery type (non-Group 27)	-1
Incorrect fasteners on side and back	-0.5
covers	
Incorrect / missing trunk platform	-0.5 to -1
Missing fuel pump vent hose	-0.5
Battery ground cable non wire braided	-0.5
Trunk lid stops / bumpers	-0.5
Non-Dzus, or missing, trunk floor hold-	-0.5
down fasteners	
Spare Tire hold down bolt (applies to	-1
Mk1 / 1A only)	
Spare Tire hold down strap and	-1
footman loops (applies to Mk2 only)	
Battery tray / plywood spacer below	-1
and Mahogany wood on the frame rail	
MkI & Mk1A Battery vent tube and	-0.5
caps	
Red Battery vent cap and hose (Lucas)	-0.5
(applies to Mk2 only)	

Missing Nylon push pins on rear wall	-0.5
(5)	
Soft top blouse snapped on Mk1	-0.5
Soft top blouse pushed on pinch welt	-0.5
on Mk1a Mk2	
Trunk side and back covers incorrect	-0.5 to -1
material and/or design	
Trunk Striker and catch assembly	-0.5
Trunk Seal incorrect	-0.5
Trunk color does not match exterior	-1